

TABLE OF CONTENTS

Non-invasive imaging of ancient foundations status in Venice (Italy) using the Electrical Resistivity Tomography technique	1
N. Abu-Zeid, G. Cocco, G. Santarato	
Performance of Some Commercial Consolidating Agents on Porous Limestones from Egypt 'Tura and Mokattam Quarry'	2
H. Ahmed, Á Török, J. Locsei	
Natural re-colonization of restored mural paintings	3
E. Akatova, L. Laiz, J.M. Gonzalez, C. Saiz-Jimenez	
Control of biofilm growth through photodynamic treatments combined with chemical inhibitors: in vitro evaluation methods	4
H.L. Alakomi, A.A. Gorbushina, W.E. Krumbein, C. McCullagh, P. Roberston, M. Saarela, K. Rodenacker	
Physical-mechanical characterization of hydraulic and non-hydraulic lime based mortars for a French porous limestone	5
M. Al-Mukhtar, K. Beck	
Atmospheric particles in an urban background: damage to building stone	6
F.J. Alonso, F. Díaz Pache, C. M. Grossi, R.M. Esbert	
The effect of fire on an earthen building	7
M. Alvarez de Buergo, Á Török, M. Gómez-Heras, M. Hajpál, R. Fort, M.J. Varas Muriel	
Sandstone weathering rates at the Angkor temples (Cambodia)	8
M.F. André	
Influence of capillary properties and evaporation on salt weathering of sedimentary rocks	9
M. Angeli, J.P. Bigas, B. Menendez, R. Hebert, C. David	
Main constraints in numerical modelling of weathering phenomena - preliminary studies	10
M. Angeli, B. Menendez, J.P. Bigas, C. David, R. Hebert	
Microclimatic factors affecting composition and distribution of phototrophic communities in monuments	11
X. Ariño, A. Gómez Bolea, C. Saiz-Jimenez	
Scientific/Documentary study of stone materials in the Palace of the Congress of Deputies in Madrid	12
M.I. Báez, J.L. Baldonado, F.D. Sanz, P. Garcés	
Characterization of marble stuccos in Writing Rooms in the Palace of the Congress of Deputies in Madrid	13
M.I. Báez, A. Rodríguez, J.L. Baldonado, M.J. García Molina	
Characterization of the metallic threads in some medieval court garments and ecclesiastical vestments by using SEM-EDS	14
I.Z. Balta, M. Donten, I. Cretu	
Laser cleaning of archaeological metal objects	15
J. Barrio, M. Arroyo, J. Chamón, A.I. Pardo, A. Criado	

The influence of the humidity on the decay of marble R. Bellopede, C. de Regibus, N.M. Luodes, P. Marini	16
Ultrasonic sound test on stone: comparison of indirect and direct methods under various test conditions R. Bellopede, L. Manfredotti	17
The decolouration of brecciated black marbles used in heritage monuments of Alicante D. Benavente, A. Bernabéu, R. Fort, J. Martínez Martínez, M.A. García del Cura	18
Cementation of porous building stone by an accelerated carbonation process A. Bernabéu, M.A. García del Cura, C. Hills, P. Carey	19
Cycles of dry and wet depositions: effects on G85 bronze exposed to rain/particulate solutions E. Bernardi, C. Chiavari, C. Martini, D. Prandstraller, L. Morselli	20
Reliability of surface analyses on ancient historical glasses R. Bertoncetto, B. dal Bianco	21
Architectural surfaces in cultural heritage - conservation and restoration of plastered façades. The "Liebfrauenkirche" in Kitzbühel, Tyrol, Austria T. Bidner, M. Pescoller, A. Diekamp, W. Hauser	22
Failures of architectural heritage due to wind effects J. Bláha, M. Drdácý, S. Pospíšil	23
Soiling and blackening in archaeological sites and monuments of Iranian cultural heritage A. Bonazza, C. Sabbioni, N. Ghedini, B. Hermosin, C. Saiz Jiménez	24
Conservation treatments on altered glass. A case study: the glass mosaic of the Porta della Mandorla in Florence S. Bracci, E. Cantisani, A. Giusti, G. Raddi	25
Climate change critical to cultural heritage P. Brimblecombe, C.M. Grossi, I. Harris	26
Evaluation of three consolidants in Miocene sandstones from the Ebro basin O. Buj, J. Gisbert	27
The integrated archaeometric and archaeological approach in the study of Late Roman 1 amphora types produced at Elaiussa Sebaste, Ayash (Turkey) F. Burrigato, M. di Nezza, A.F. Ferrazzoli, M. Ricci	28
Digital image mapping as analysis and evaluation tool in heritage conservation and restoration processes R. Bustamante, D. Sanz, N. Prendes, I. Salto-Weis	29
Study of natural cements from the French Rhône-Alpes region E. Cailleux, E. Marie-Victoire, D. Sommain	30
Surface finishes on historic buildings in the Salento peninsular (Apulia, South Italy): early data A. Calia, G.E. De Benedetto, M. Lettieri, M. Masieri, G. Quarta	31

The Saint-John Sepulchre at Brindisi (South Italy): identification and provenance of marbles	32
A. Calia, M.T. Giannotta, G. Quarta, A. Cimino	
Modeling the penetration of SO₂ within the pores of calcareous stones and the concentration of gypsum in the near surface layer	33
D. Camuffo, M. Del Monte, R.A. Lefèvre, P. Ausset, E. Pagan	
Definition of protection areas in a prehistoric art cave (Tito Bustillo cave, N Spain)	34
J.C. Cañaveras, S. Cuezva, E. Sanz-Rubio, S. Sánchez Moral	
Experimental weathering of carbonate rocks promoted by simple and combination of salts	35
C. Cardell Fernández	
The pottery of a peasant community of Las Médulas (León, Spain): archaeometric study of the Orellán site, 1st - 2nd centuries AD	36
N. Carmona, M. García-Heras, M.A. Villegas, M.D. Fernández-Posse, J. Sánchez-Palencia	
Characterization of historical and model lead glasses by LIBS	37
N. Carmona, M. Oujja, S. Gaspard, M. García-Heras, M.A. Villegas, M. Castillejo	
Valuation of the effectiveness of an antigraffiti product applied to "Blanco Paloma" Limestone	38
P.M. Carmona-Quiroga, S. Martínez-Ramírez, M.T. Blanco-Varela, R. Fort	
Re-use hypothesis for the valorization of the castle of Maddaloni and its towers	39
A. Catalano, M. Cristiano	
Nanotechnologies for the conservation of waterlogged wood: the Vasa case studies.	40
D. Chelazzi, R. Giorgi, P. Baglioni	
Where it was, how it was	41
D. Chizzoniti, G. Canella, E. Bordogna, P. Bonaretti, L. Monica	
A microclimatic study for the design of new shelters for the archaeological site of Castellammare di Stabia - Naples	42
M. Citterio, E. Giani	
Diagnostic studies aimed to conservation works in S. Fedele church (Milan)	43
C. Colombo, C. Conti, M. Realini, A. Sansonetti	
Characterization of mortars used in construction and rehabilitation of Aeminium Criptoportico	44
J. Coroado, A. Velosa, R. Silva, P. Redol, A. Alarcão	
Characterization of Roman Fibulae from a Parisian excavation site using electrochemical techniques	45
V. Costa, K. Leyssens, N. Richard	

Impact of environmental conditions on metallic artifacts from the treasure rooms of Reims Cathedral	46
V. Costa, A. Texier, D. de Reyer	
The stone elements of "Via Krupp" in Capri, survey and conservation hypothesis	47
M. Cristiano	
Reevaluating the cultural value of Segovia's Romanesque churches through biodiagnosis	48
A. de los Ríos, V. Galván, C. Ascaso	
Restoration of the façades at the Moorish Pavilion	49
B.C.G. de Lourenço	
EIS Investigation of resin and wax degradation on different atmospheres of the Museum of Ethnology and Archaeology of the University of São Paulo	50
H.G. de Melo, A.C. Neiva, R.P. Bendezú-Hernández, A.F.C. Ribeiro, S.C. Lima	
EIS Characterization of artificial patinas applied on copper and bronze samples	51
H.G. de Melo, A.C. Neiva, R.P. Bendezú-Hernández, C.F. Salgueiredo	
Causes of salt decay and repair of plasters and renders of five historic buildings in Portugal	52
T. Diaz Gonçalves, J. Delgado Rodrigues, M. Marinho Abreu, A.M. Esteves, A. Santos Silva	
Intervention in the sector of Porta de Vila in the city walls of Lagos (Alagarve, Portugal): Historical, technical and constructive aspects	53
M. Díaz Guardamino, E. Moran, T. Valente	
Gothic dolomitic mortars with slag fragments from the Liebfrauenkirche and the Andreas Kirche in Kitzbühel, Tyrol, Austria	54
A. Diekamp, T. Bidner, J. Konzett, P.W. Mirwald	
Impact of tourism on historic materials, structures and environment	55
M. Drdácý, T. Drdácý	
Non-invasive survey of detachment of historic rendering	56
M. Drdácý, J. Lesák	
Analysis and restoration of an exterior plaster floor of the 19th Century	57
M. Drdácý, Z. Slízková, A. Zeman	
Maastricht limestone: a regionally significant building stone in Belgium and the Netherlands. Extremely weak, yet time-resistant	58
C.W. Dubelaar, M. Duser, R. Dreesen, W.M. Felder, T.G. Nijland	
Urban soiling on calcarenite of El Salvador church, Sevilla, Spain	59
A. Durán Benito, J. García Talegón, M. González Sánchez, M.C. Jiménez del Haro, A.C. Íñigo, A. Justo, E. Molina	
Study of copper alloys alteration by direct human action	60
A. Durán Benito, A. Justo Erbez, M.C. Jiménez de Haro, J.L. Pérez Rodríguez, J.M. Martínez Blanes, B. Sigüenza, J.C. Pérez Ferrer	

Simulated aging of lime mortars - a mechanical property, structural and compositional study	61
A. El-Turki, R. J. Ball, G. C. Allen	
Geopolymerization as a novel method to consolidate earthen architecture: preliminary results	62
K. Elert, C. Rodriguez Navarro, E. Sebastian	
The restoration of modern architecture: diagnostic and pre-project activities	63
F. Fernandez, V. Ruggirello	
Metallographic studies of copper based scraps from the Late Bronze Age Santa Luzia archaeological site (Viseu, Portugal)	64
E. Figueiredo, M.F. Araújo, R. Silva, F.M. Braz Fernandes, J.C. Senna-Martinez, J.L. Inês Vaz	
Weathering and conservation of rhyolite tuff from the area of Eger, Hungary	65
L.Z. Forgó, Á Török	
The Royal Hotel of the Poor. A Giant that Awakens	66
V. Gambardella	
Microenvironments in the inner and outer parts of the Zamora Cathedral	67
J. García Tiegón, M. González Sánchez, S. Vicente-Tavera, A.C. Iñigo, V. Rives	
Pulsed laser deposition of polymers doped with fluorescent probes. Application to environmental sensing of cultural heritage	68
S. Gaspard, E. Rebollar, M. Oujja, M. Castillejo, T. Corrales, M.M. Villavieja, P. Bosch, S. Georgiou	
Integrated analysis and interpretation of architecture changes and vulnerabilities by combined use of historical sources and infrared thermography: the study case of San Francesco convent near Montella (AV), Southern Italy	69
E. Gheraldi, G. Colesanti, C. Dolce	
Natural vs built environment: integrated methodological approach for reconstruction of connections between urban transformations and natural environment of the ancient Tursi Rabatana citadel, S. Italy	70
E. Gheraldi, M. Lazzari, M. Lapenna, A. Loperte	
Spectroscopical analysis using a hybrid LIBS-RAMAN system	71
A. Giakoumaki, I. Osticioli, D. Anglos	
The use of an environmental data sheet: the case of Musei Civici of Pesaro (Italy)	72
E. Gheraldi, A. Giovagnoli, M.P. Nugari, E. Ruschioni, L. Gordini	
Greek painted chamber tomb in Taranto (South Italy): characterization of plasters and pigments	73
M.T. Giannotta, G. Quarta	
Stone materials from Tudela cathedral (Navarra, Spain). Characterization of stone and evaluation of deterioration processes	74
J. Gisbert, P. Navarro, O. Buj, B. Franco, N. Mateos, B. Bauluz	

Influence of simulated heating regimes on the crystallisation morphologies of sodium chloride (NaCl)	75
M. Gómez-Heras, R. Fort	
Evolution of porosity in Hungarian building stones after simulated burning	76
M. Gómez-Heras, M. Hajpal , M. Álvarez de Buergo, Á Török, R. Fort, M.J. Varas	
Current advances in the molecular characterization of microbial communities on cultural heritage	77
J.M. Gonzalez, C. Saiz-Jimenez	
BIODAM - Novel polyphasic approaches to biofilm control using molecular techniques	78
A. A. Gorbushina, W.E. Krumbein, J. Marquardt	
Investigations in Islamic tapia wall construction in the South of Spain	79
A. Graciani García, A. Barrios Padura, M.Á. Tabales Rodríguez, J. Barrios Sevilla	
Products of historical concrete degradation: qualitative and quantitative study	80
M. Gregerová , P. Pospíšil	
Technological features of glazed Protomajolica ware from Benevento (Italy)	81
C. Grifa, V.Morra, A. Langella, G. Cultrone, E. Sebastian	
Sulfate and carbon compounds in black crusts from the Cathedral of Milan and Tower of London	82
C. M. Grossi, P. Brimblecombe, A. Bonazza, C. Sabbioni, J. Zamagni	
The succession of biofilms on building stone and its possible impact on biogenic weathering	83
M.Hoppert, S. König	
Low pressure abrasive cleaning on historic building materials	84
M. Iglesias, B. Gea, J.L. Prada, N.Guasch	
Novel species of the genus Phyllobacterium in the biofilms covering the walls of Roman Catacombs	85
V. Jurado, J.M. Gonzalez, L. Laiz, M.C. Portillo, M. Hernandez Marine, C. Saiz-Jimenez	
Experimental and numerical evaluation of a new method for joining together fragmented structural members	86
S. K. Kourkoulis, M. Mentzini, E. Ganniari-Papageorgiou	
Johannes Aquila and the technique of Gothic mural paintings (14th century)	87
A. Kriznar , A. Ruiz-Conde, P.J. Sánchez-Soto	
Microbial assessment of the biological colonization on roofing tiles	88
L. Laiz, J.M. Gonzalez, M.C. Portillo, M.F. Gazulla, E. Sanchez, C. Saiz-Jimenez	
Methodology of study of the bioleaching of a cement matrix	89
H. Lajili, J.R. Degorce Dumas, C. Grambin Lapeyre, J. Roussy, P. Devillers, J.P. Bournazel	

VHR satellite images for the knowledge and the valorization of cultural landscapes: the medieval deserted villages in Basilicata (Southern Italy)	90
R. Lasaponara, A. Lanorte, M. Masini, M.R. Potenza	
Non-destructive wood mechanical properties evaluation under continuous vibration: application to conservation of musical instruments	91
S. Le Conte, S. Vaiedelich, M. François	
The stock of materials at risk of air pollution deterioration in the centre of Paris inscribed on the UNESCO list of World Cultural Heritage	92
R.A. Lefevre, A. Ionescu	
Integration of NDT techniques for the restoration of a rose-window: case Study	93
D. Liberatore, N. Masini, A. Calia, F.T. Gizzi, L. Nuzzo, E. Rizzo, G. Spera	
Weathering rates of bronze outdoor sculpture	94
R. Livingston	
Assessment of performances of a "facing" process	95
S. Logel, C. Thomachot	
The use of protective glazing to prevent dust deposition on stained-glass windows	96
T. Lombardo, A. Chabas, R. Lefèvre, P. Ausset, H. Cachier, O. Favez, K. Oikonomou, A. Ionescu	
Kinetics of sodium sulfate efflorescence as observed by humidity cycling with ESEM	97
P. López-Arce, E. Doehne	
The Restoration of a stone bridge in semiarid environment: Puente Viejo of Elche (SE Spain)	98
M. Louis, M.A. García del Cura, A. Bernabeu, A. La Iglesia, Y. Spairani, J.A. Huesca, R. Prado	
Biological coloration of calcareous stone surfaces in Portuguese ecclesiastic monuments	99
P.M.L. Lourenço, M.L. Tavares, F. de Llera Blanes, P. Pereira	
Conservation condition of the Wall of Talamanca de Jarama, Madrid, Spain	100
J. Luque, M.J. Varas, E.M. Pérez Monserrat, R. Fort	
Comparison of Shelters' performance at Joya de Cerén, El Salvador	101
S. Maekawa	
Comparison of "in-situ" mechanical tests on masonry mortars: sphere impact and controlled penetration test	102
A.C. Magalhães, M.R. Veiga	
The "contact sponge": study of the applicability of a new and simple methodology	103
M. Manfredotti, P. Marini	
Natural stones used in Royal House of Piedmont (Italy)	104
P. Marini, C. Mossetti	

Mortar analysis of samples from the Royal Botanic Gardens, Sydney T. Markopoulos, D. Dragovich, V. Perdikatsis, E. Repouskou	105
Study of old and rehabilitation mortars by common analytical techniques S.F. Marques, V.M. Ferreira, J.A. Labrincha, L.M. Silva	106
Comparative study of building materials in the Patio de las Doncellas in Seville's Reales Alcázares (Spain) J.J. Martín del Río, F.J. Alejandre, G. Márquez, F.J. Blasco	107
Weathering of speleothems by microbial activity. An example from Castañar de Ibor Cave, Cáceres, Spain A. Martín Pérez, A.M. Alonso Zarza, I. Gil Peña, E. Martínez Flores, P. Muñoz Barco	108
Study by SEM/EDX and FT-IR spectroscopy of resin bound mortars based on hydraulic and synthetic binders combined with "Tosca de Rocafort" and Bateig stones X. Mas i Barberà, M.T. Domenech Carbó, J.L. Roig Salom	109
Catalogue of building techniques of vernacular architecture: case study in Southern Italy N. Masini	110
Monitoring salt systems in monument stones: comparing two electrochemical methods A. Maurício, C. Figueiredo, L. Aires-Barros	111
Calcium loading of building sandstones by lime rendering: implications for decay S. McCabe, B.J. Smith, P.A. Warke	112
The application of geostatistical techniques in weathering studies of natural building stone J. McKinley, P.A. Warke, B.J. Smith, J.M. Curran	113
Microbial biofilms inside historic stone C.J. McNamara, K. Bearce, T.D. Perry IV, R. Mitchell	114
Preserving cultural heritage, the local agenda on the global stage. The impacts of international tourism E. Meehan	115
Analysis of parchment book-binding by infrared thermography F. Mercuri, F. Scudieri, S. Paoloni, M. Marinelli	116
The treatment of weathered Globigerina Limestone: the surface conversion of calcium carbonate to calcium oxalate T. Mifsud, J. Cassar	117
Mapping and characterization of a green biofilm inside of Vilar de Frades Church (Portugal) A. Miller, M.F. Macedo	118
The DRMS drilling technique with pilot holes J-M. Mimoso, D. Costa	119

Diagnostic techniques to assess mechanical characteristics of historical timber	120
J. Minster, M. Drdácý, I. Jirovsky, M. Kloiber, M. Micka, Z. Slízková, P. Václavík	
Oil-Paintings of Bartolomé Esteban Murillo (1618-1682) using an unusual support: polished obsidian	121
R. Moreno, A. Ruiz Conde, P.J. Sánchez Soto	
Inheritance in form and process of rock surface evolution: evidence from shore platforms	122
D. Mottershead, R. Inkpen	
The long term effects of a water repellent treatment on a volcanic tuff	123
U. Müller, F. Weise, S. Grell	
Fire safety requirements and burning behaviour of textiles in renewed historical buildings	124
J. Muskalska, M. Ornat, K. Robaczynska	
Lime-based repair mortars - influence by surface working methods on behaviour and durability of mortar	125
M. Myrin, K. Balksten	
A Case Study on the Evaluation of consolidation treatments of Gotland Sandstone by use of ultrasound pulse velocity measurements	126
M. Myrin, K. Malaga	
Considering spurious peaks in the EDXRF analysis of metallic pre-Columbian pieces of the Museum of Ethnology and Archaeology of the University of Sao Paulo	127
A. C. Neiva, J.N. Dron, S.C. Lima	
Analysis of proteins found in wall paintings using laser induced fluorescence spectroscopy	128
A. Nevin, D. Anglos, S. Cather, C. Fotakis	
Building stones from a muddy delta: native natural stone from the Netherlands	129
T. G. Nijland, C.W. Dubelaar, H.J. Tolboom, R.P.J. Van Hees	
Retables' constructive systems - N.S. Necessidades and N.S. Lapa churches	130
M.A. Nunes, A. Valle, S.C.B. Nappi	
The effects of fire and heat on natural building stones: first results from the Gröden Sandstone	131
U. Obojes, A. Saxer, P. Tropper, P.W. Mirwald	
Application of weathering susceptibility index to salt damage on a brick monument	132
C. T. Oguchi, Y. Matsukura, H. Shimada, N. Kuchitsu	
The Horus temple at Edfu (Egypt): the local economic and social benefits of conservation	133
J. Ordóñez García, C. Cardell Fernández, A. Jiménez Serrano	
Role of water reducing agents in mortar behaviour	134
H. Paiva, J.A. Labrincha, V.M. Ferreira	

Preliminary studies on the development of lime based mortars for adobe masonry H. Paiva, E. Marques, A. Velosa, J. Coroado, J.A. Labrincha, V.M. Ferreira	135
Characterization of bacterial community in indoor environment F. Palla, S. Marineo, L. Anello, G. Lombardo	136
The last period of "Buen Retiro" porcelain factory C. Pascual, P. Recio, S. De Aza, F.J. Valle, E. Criado, A.H. De Aza, R. Martínez	137
Materials and techniques used in the works of art from Paulistas Church in Lisbon (Portugal) A. Pereira, A. Miller, E. Figueiredo, S. Trindade	138
Geomonumental Routes: a useful tool for the popularization of architectural heritage E.M. Pérez Monserrat, M.J. Varas Muriel, M. Gómez-Heras, M. Álvarez de Buergo, R. Fort	139
Accelerated ageing by salt crystallisation: assessment of a suitable laboratory methodology T. Poli, M. Positano, L. Toniolo	140
Studies of the efficiency of the biocide "BIOTIN N" incorporated in artificial stone composed of ground natural stone and a commercial acrylic resin concerning the growth of algae. R. Portero de la Torre, F.C. Bolívar Galiano, X. Mas i Barberà, M.T. Domenech Carbó, J. Petermann, B. Uceda	141
Diversity of sulfate-reducing bacteria as an example of the presence of anaerobic microbial communities in Altamira Cave (Spain) M.C. Portillo, J.M. Gonzalez, C. Saiz-Jimenez	142
Surface degradation of complex architectural form due to atmospheric pollution S. Pospíšil, M. Drdácý, Z. Slížková, D. Knotková, P. Delpech	143
A comprehensive study on the discoloration associated with laser cleaning of stonework P. Pouli, G. Totou, C. Fotakis, S. Gaspard, M. Oujja, M. Castillejo, C. Domingo	144
The Romanesque Façade of Sant Martí de Puig-Reig (Barcelona): chromatic layers and conservation treatments on stone J.L. Prada, N. Guasch, M. Iglesias, M. Badia	145
Brick degradation. Salt exudation cartography N. Prendes, E. Menéndez	146
Applications of laser vibrometry analysis to damage detection in masonry structures F. Prieto, M. Martin, M. Viola	147
"New natural stone" for the reconstruction of Charles Bridge in Prague R. Prikryl	148
Czech limestone in Baroque Architecture: resources and deterioration R. Prikryl, J. Prikrylová	149

Porosity and permeability of sandstones R. Prikryl, Z. Weishauptová	150
Characterization and influence of the ancient mortars on the decay of medioeval castle of Barisciano, L'Aquila (Italy) R. Quaresima, H. Corpora, R. Volpe	151
Laser removal of organic coatings: fundamental studies and applications to cultural heritage E. Rebollar, M. Oujja, S. Gaspard, M. Castillejo, G. Bounos, S. Georgiou	152
The restoration of a Codex on Arab Paper (1293-94) M.L. Riccardi, C. Casetti Brach	153
Deteriorations forms present in the covering materials of the Monastery of Lorrvão, Portugal - Characterization and causes M. Rodrigues, M.L. Tavares, M.J. Basto, F. de Llera Blanes	154
Study for the determination of the pathologies in the constituent materials of the Milagros Aqueduct (Mérida) M.I. Mota López, J.M. Ávila Macías, I. Rodríguez Maribona	155
Recovery of phototrophic biofilms after biocide treatment in the tourist cave "Salnitre de Collbato" (Barcelona, Spain) M. Roldán, M.J. García, A. Navarro, M. Hernandez Marine	156
Fungal biodeterioration of sandarac varnish J. Romero Noguera, I. Martín Sánchez, F. Poyatos Jiménez, F.C. Bolívar Galiano, M.A. Fernández Vivas	157
Fabric dependence of length change behaviour induced by ice crystallisation in the pore space of natural building stones J. Ruedrich, S. Siegesmund	158
Limestone masonry performances in correlation to face components, bed mortars, and climatic decay R. Ruggeri	159
The use of additives (phosphonates) as inhibitors for the crystallization of magnesium sulfate E. Ruiz Agudo, C. Rodríguez-Navarro, E. Sebastian	160
Weathering and conservation of mural paintings in the church "Nuestra Señora de las Nieves" (La Rinconada, Sevilla, Spain) A. Ruiz Conde, M. Arjonilla, G. Durán, J.C. Rivero, P.J. Sánchez Soto	161
Global climate change impact on built heritage and cultural landscapes C. Sabbioni, M. Cassar, P. Brimblecombe, J. Tidblad, R. Kozłowski, M. Drdáký, C. Saiz Jiménez, T. Grontoft, I. Wainwright, X. Ariño	162
Origin of gypsum crusts in monuments built with granitic material in A Coruña, NW Spain J. Sanjurjo, J. R. Vidal Romani, C. A. S. Alves	163

Stone portals in Naples ancient centre. Degradation and maintenance C. Sansone	164
Evaluation of protective and consolidant treatments on Angera Stone in S. Fedele Church (Milan) A. Sansonetti, T. Poli, M. Realini, D. Gulotta	165
Characterization of Roman mortars from the historical town of Mertola A. Santos Silva , J.M. Ricardo, P. Adriano, M. Salta, J. Mirão, A.E. Candeias, S. Macias	166
Texture and residual strain in Carrara marbles measured by TOF neutron diffraction Ch. Scheffzük, S. Siegesmund, A. Hoffmann, D.I. Nikolayev	167
Influence of admixtures in the properties of hydraulic lime based mortars M.P. Seabra, J.A. Labrincha, V.M. Ferreira	168
Stone decay. A multidisciplinary case study: the columns of the Ducal Palace in Urbania P. Semprini, J. Arduini, L. Baratin, U. Giostra, M. Maione, F. Mangani	169
Rapid, catastrophic decay of building limestones: Thoughts on causes, effects and consequences B. Smith, H.A. Viles	170
Weathering of archaeological masonry: from the evaluation to the restoration A. Sposito, F. Fernandez	171
Salt accumulation in historic and repair mortars M. Stefanidou, I. Papayianni	172
Crystal growth in porous materials: influence of supersaturation and crystal size M. Steiger	173
Traditional and modern lime-based plaster and coatings - do additives enhance biodeterioration? K. Sterflinger	174
Biodeterioration of buildings and works of art - practical implications on restoration practice K. Sterflinger, H. Sert	175
Microbial diversity on paintings and engravings in Doña Trinidad Cave (Ardales, Spain) F. Stomeo, L. Laiz, J.M. Gonzalez, C. Saiz-Jimenez	176
Conservation of old renderings - the consolidation technique through traditional and sustainable materials: the lime water (a study methodology) M.L. Tavares, M.R. Veiga	177
Dilation of bricks submitted to frost action: field data and laboratory experiments C. Thomachot , N. Matsuoka, N. Kuchitsu, M. Morii	178

Use of portable X-ray fluorescence for monitoring elemental concentrations in surface units on roadside stone at Worcester College, Oxford	179
M. Thornbush, H. Viles	
Validation of a new portable integrated system for "in situ" evaluation of stone mechanical properties	180
P. Tiano, S. Rescic, G. Exadaktylos, E. Papamichos, E. Valentini	
The façade of Milan cathedral: a case of diagnosis for the intervention	181
L. Toniolo, F. Casadio, C.M. Zerbi	
Hungarian taverne: Weathering forms and durability.	182
Á Török	
Weathering experiments on alpine marbles-comparison on exposure studies and laboratory experiments-experimental setup and preliminary results	183
M. Unterwurzacher, T. Bidner, P.W. Mirwald	
Public Perception and Optical Characterization of Degraded Historic Stone and Mortar Surfaces	184
J. Valach, J. Bryscejn, M. Drdácý, Z. Slizková, D. Vavřík	
Depth of penetration of humid air into stone and subsequent mobilization of deliquescent salts by humidity cycling: NMR analysis of NaCl in limestone	185
G.H.A. van der Heijden, E. Doehne, L. Pell	
Earthquake-resistant structural design guide: Retrofit conservation of Doctrinal Chapels of the Oyon region (Peru) based on performance criteria	186
J. Vargas-Neumann, M. Beas, P. Navarro Grau, J. Velásques	
Patinas in the Architectural Heritage of Lerma, Burgos (Spain)	187
C. Vazquez-Calvo, M. Alvarez de Burgo, R. Fort	
Managerial aspects of a project of reutilization: the Scuola Grande della Misericordia	188
M. Vecco	
Characterization of stone and mortar decay - Casa Major Pessoa, Aveiro	189
A. Velosa, J. Coroado, F. Rocha	
Historical technological and architectural aspects in building recovery of a "Villa Liberty" in Palermo, Italy	190
R.M. Vitrano	
The "technological parameters" of heritage conservation: Factors of decay - instruments of building recovery and prevention measures	191
R.M. Vitrano	
Microwave treatment for woodworm disinfection in large-format works of art	192
V. Vivancos-Ramón, E. Pérez-Marín, L. Nuño-Fernández, J.V. Balbastre-Tejedor, A.T. Zona-Ortiz	
Identification of the provenance of natural stone used as roofing material in Scotland	193
J.A. Walsh	
Assessment of stone durability: impact of test conditions	194
P.A. Warke, B.J. Smith, J. McKinley	

Salt-weathering, conservation techniques and strategies to protect the rock cut facades in Petra/Jordan	195
W. Wedekind, J. Ruedrich	
Micro x-ray computer tomography (μ-CT) for the low invasive analysis of stone	196
F. Weise, U. Müller, J. Goebbels	
Biochemical deterioration mechanisms of cementeous matrix by fungi : preliminary results	197
V. Wiktor, R. Guyonnet, P. Grosseau, E. García Díaz, A.M. Danna, B. Guilhot	
Salt distribution within experimentally weathered sandstone: some preliminary observations	198
J.S. Wright	
Granite soiling in Aberdeen, UK: pollutants, stone characteristics and mortars	199
M.E. Young	
Author Index	201